

OCTANS NANO

SOFTWARE PACK 1.06

RELEASE NOTES



These Release Notes detail improvements and bug fixes of OCTANS NANO Pack 1.06.

Please read these notes carefully before installing the software.

PACK CONTENT

OCTANS NANO Pack 1.06 Details

QNX	3.02
CINT Loader	5.10
CINT Firmware	4_12_3
Web MMI	OCTANS NANO 5.61-1.113
DSP Loader	3.2
DSP Firmware	3_20_1

Compatibility

This software pack can only be loaded on systems with CINT Loader 3.9 or above and CDSP Loader 2.3 or above. For older configurations, please contact IXBLUE support.

WHAT'S NEW

The following are the improvements & bug fix since OCTANS NANO pack 1.05.

Improvements

- Add new input protocol : MINIFOG_GPS_MSG
- Add new output protocol : MINIFOG_OTG_MSG8

Bug fixes

- NA

CUSTOMER SUPPORT

For any additional questions feel free to contact our worldwide 24/7 customer service:

By e-mail: support@ixblue.com

By phone: +33 (0) 1 30 08 98 98 for EMEA

+1 508 975 4640 Ext 1 for the US

+65 6747 7027 for Asia